
Images shown are of the flooring throughout the building.

- Planks are- separating, warping, and damaged.
- Some doorways are missing door strips.





















































The following images show damage to- ceiling, drywall, interior paneling, and electrical components.



































